


FTDI USB

Use FT_PROG utility and set CBUS3 as GPIO

Xilinx Virtual Cable with FT220X

It is possible to use FT230XS (USB to RS232 convertor) as well.

XILINX JTAG



MECHANICAL

- M100 Screw M3x12
- M101 Screw M3x12
- M102 Screw M3x12
- M103 Screw M3x12
- M104 Washer M3
- M105 Washer M3
- M106 Washer M3
- M107 Washer M3
- M108 Standoff M3x5
- M109 Standoff M3x5
- M110 Standoff M3x5
- M111 Standoff M3x5
- M112 JUMPER

MECHANICAL

FOR NEXT RELEASE

There should be a resistor from VCC_TARGET to ground. The input is a little too much sensitive.

Firma		Author	
MLAB		MIHO	
Size	Project Name	Schematic Name	Rev
A4	XVC_FT220X01A	Main Page	1.00
Date:	Friday, December 28, 2012	Sheet	1 of 1
2		1	